AEE/ESD/SBR 68/16-17 Dt 30-6-16

RMR No. 265 8/9/16

170243

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

M.A.R. 57 (Rule 116)

Measurement Book

No. C/09

Serial No. 1st & final

Name of work. Work maintenance of wood using tractor, SPT and labour in wood-II in ESD (Supervision) From To

Name of Contractor of nature of Agency R. Mangalraju.

Date of commencement of work

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Job code — 013-13-0000 21 Work order no — EE/00/WO/51/13-14 dt -19/07/2013 Date of Recording 6.						
①	Supply of 50 HP tractor on daily rate basis to the required place as per the direction of the Engineer in charge TMR Qty noted pg no - 170247				343 / 342	× 2240 = 768320 / 766080 = 00	

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
(1)	Supply of the labour heavy maseloon to the liquing plan as per the direction of the Engineer in charge						
	Qty vide pg no — 170252				3313 X 170 = 3303	563210.00	
						561510=00	
(2)	JCB excavation Complete as per Specification						
	Qunty pg no — 170253				7 X 6500 =	45500.00	
(4)	DPPm Complete as per Specification						
	Qunty pg no — 170253				7 X 1920 =	13440.00	
						Total 1390470.00	
						1386530=00	

Verified as Free

writing pg

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

Audited and admitted for Rs. 1386530=00
Passed by Cheque for Rs. 123625=00
153905=00
Accounts Superintendent
Exec. Engineer

170244

M.A.R. 57 (Rule 116)

Measurement Book No. C/09

Serial No. ..... by ..... From ..... To .....

Name of work .....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Certificate :						
	The contractor done the work satisfactorily						
	The contractor removed all the debris from the premises.						

Thulli

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.